

PERFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING

1. Name of the school Mount Jitendra Zee school
2. Location Q. A, Rishi Vihar, Shimla Bypass Road
Mehrawal
3. Plot Area 8648 sqmtr.
4. Plinth Area 6347 sqmtr.
5. No. of stories 4 stories.
6. Year of Construction 2011
7. Weather the building has been constructed under the supervision of the qualified Engineer, if so.
- a) Name of the engineer with qualification _____
- b) Address _____
- c) Set of structure drawing used in construction _____
8. Weather the building has been constructed for the purpose of
- a) School (yes/No)
- b) Residential Purpose (or) (yes/No)
- c) Concerted for school (yes/No)
9. Material used for roofs:
- a) R.C.C Slab (yes/No)
- b) R.S joint & Battens (yes/No)
- c) Wooden Joint & Battens (yes/No)
10. Material Used for wall
- a) Mud Morter (yes/No)
- b) Cement Mortet (yes/No)
- c) Plaster Lime Moret (yes/No)
- Cement Morter (yes/No)

11. Flooring

- a) Vitrified Tiles/Stone (yes/No)
- b) Terrazo (yes/No)
- c) Brick paving (yes/No)

12. A detailed drawing indicating dimensions of the rooms & location of doors and windows is attached.

13. General

- a) In case of double story building 1.5 meter width are constructed or not (yes/No)
- b) Whether classroom are provided two door system (yes/No)
- c) Whether fire safety measure have been adopted and are in working condition (yes/No)

Dated:

(For the use of the NAGAR NIGAM DEHRADUN)


a) I P. S Panwar A.E along with Rajender Singh A.A.E have visited this school on 05/12/2024 and have inspected it from all angles of safety and found it fit for normal use as school building.


b) In case any addition alteration, extension or modification of this building is to be carries out, it should be carried out under the supervision of technical qualified engineer and after its completion this certificate may again be obtained from the undersigned.

c) In case the building is affected by flood or if there is settlement to walls foundation edging or roof, immediate of the undersigned be arranged to check the stability and safety of the building

d) The building can be safety occupied for normal use up to 04/12/2025

e) Inspection fee amounting to Rs. — has been deposited by the school vide G.R.No. — Dt —


अधिसारी अभियन्ता
नगर निगम देहरादून
Countersigned


सहायक अभियन्ता
नगर निगम देहरादून
Sub Division Engineer